DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 1.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-022355

Address: 333 Burma Road **Date Inspected:** 29-Mar-2011

City: Oakland, CA 94607

Project Name: SAS Superstructure **OSM Arrival Time:** 730 **OSM Departure Time:** 1600 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: American Bridge/Fluor Enterprises, a JV **Location:** Job Site

CWI Name: N/A**CWI Present:** Yes No

Inspected CWI report: Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A **Qualified Welders:** Yes No N/A **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No

Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component:** S.A.S. components

Summary of Items Observed:

The Quality Assurance Inspector (QAI), Scott Croff, was present at the Self Anchored Span (SAS) job site to observe the scheduled fabrication and welding of components for the SFOBB project.

The QAI reviewed contract related documents including the submitted and approved Welding Quality Control Plan (WQCP) and approved revisions to the WQCP. The QAI completed the review of welding report submittal 1536R53. The QAI noted that Category B comments apply to the submittal. Reference the TL-20 report for additional information.

Summary of Conversations:

The QAI relayed the status of document reviews to the QAI Lead Bill Levell. Except as described above, there were no other notable conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Nina Choy (510) 385-5910, who represents the Office of Structural Materials for your project.

Inspected By: Croff,Scott Quality Assurance Inspector **Reviewed By:** Levell, Bill **QA** Reviewer